HI-VIZ REVERSIBLE JACKET



MAXIMUM PÉRFORMANCE & COMFORT JK-SF-1154



Hood Provides extra protection against the elements.

Front Closure YKK zipper with a reversible slider for smooth operation on both sides.

Multiple Pockets: Zippered pockets on the front for secure storage of essentials.

> Reflective Tape: Strategically placed reflective tape on the outside shell enhances visibility in low-light conditions.

> > Ribbed cuffs and bottom hem for a snug, comfortable



COMPOSITION & FEATURES:

Outside Shell: J-HV-P-W757501-2 Poly Stretch Twill 2-layer Hi Vis

Yellow 100% Polyester (wr,pu Milky Transfer Membrane) Gsm 17<u>0.</u>

Contrast Fabric: Poly Stretch Twill Fbg Grey 100% Polyester (dwr)

COLOR WAYS

Hi-Viz Yellow/Grey

Gsm 170. Wadding: Wadding White 150 Grams. Rib 2x1 Grey 98% Cotton 2% Spandx Gsm 480

High-vis clothing, whose effectiveness no longer sufficaes due to soiling, ageing or reduction of the luminosity of the materials used, must be replaced. Wash inside out. Machine Wash 40°C. Do not bleach. Low tumble dry. Do not Iron.





It is recommended to check that the garments are suitable for the intended use. Carefully inspect the garment before using or reusing them







Hi Vis Road Safety Night Engineering Works

Cold Weather

Maintenance & Repair

HI-VIZ REVERSIBLE Jacket



MAXIMUM PERFORMANCE & COMFORT

JK-SF-1154 Hood Provides extra protection against MEC the elements. Front Closure YKK zipper with a reversible slider for smooth operation on both sides. Multiple Pockets: Zippered pockets on the front for secure storage of essentials. Ribbed cuffs and bottom hem for a snug, comfortable

COMPOSITION & FEATURES:

Inner Side: Double Knit Fleece Hi Vis Yellow 100% Polyester Gsm 280

The Hi-Viz Reversible Jacket is designed for those who need

both visibility and versatility. Ribbed cuffs and bottom hem provide

COLOR WAYS

Hi-Viz Yellow/Grey

a secure fit, making this jacket ideal for work environments where safety and adaptability are key.

High-vis clothing, whose effectiveness no longer sufficaes due to soiling, ageing or reduction of the luminosity of the materials used, must be replaced. Wash inside out. Machine Wash 40°C. Do not bleach. Low tumble dry. Do not Iron.







It is recommended to check that the garments are suitable for the intended use. Carefully inspect the garment before using or reusing them







Hi Vis Road Safety **Night Engineering Works**

Cold Weather

Maintenance & Repair